Capital Fund Program - Five-Year Action Plan

Status: Submitted Approval Date: Approved By: 02/28/2022

Part	Part I: Summary						
PHA	Name: Pike County Housing Authority	Locality (City/Co X) Original 5-Ye	=	Revised 5-Year I	Plan (Revision No:)	
PHA Number: IL071							
Α.	Development Number and Name	Work Statement for Year 1 2024	Work Statement for Year 2 2025	Work Statement for Year 3 2026	Work Statement for Year 4 2027	Work Statement for Year 5 2028	
	PITTSFIELD (IL071000001)	\$596,000.00	\$596,000.00	\$596,000.00	\$596,000.00	\$596,000.00	

Part II: Supporting Pages	- Physical Needs	Work Statements (s)
----------------------------------	------------------	---------------------

Work Statement for Year

Work State	ment for Year 1 2024			
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	PITTSFIELD (IL071000001)			\$596,000.00
ID0021	Operations(Operations (1406))	Operations		\$149,000.00
ID0022	A&E Costs(Contract Administration (1480)-Other Fees and Costs)	A&E Costs		\$45,000.00
ID0032	Dwelling Unit Demolition, 71-13 Pittsfield(Dwelling Unit - Demolition (1480))	Dwelling Unit Demolition, 71-13 Pittsfield		\$201,000.00
ID0041	Dwelling Unit Demolition, 71-9 Pittsfield(Dwelling Unit - Demolition (1480))	Dwelling Unit Demolition, 71-9 Pittsfield		\$201,000.00
	Subtotal of Estimated Cost			\$596,000.00

Work Statement for Year 2

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	PITTSFIELD (IL071000001)		1	\$596,000.00
ID0002	Operations(Operations (1406))	Operations		\$149,000.00
ID0009	A&E Costs(Contract Administration (1480)-Other Fees and Costs)	A&E Costs		\$45,000.00
ID0028	Accessibility Improvements, 71-1 Barry(Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Site Work (1480)-Other)	Accessibility Improvements, 71-1 Barry		\$50,250.00
ID0042	Accessibility Improvements, 71-2 Barry(Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Site Work (1480)-Other)	Accessibility Improvements, 71-2 Barry		\$50,250.00
D0043	Accessibility Improvements, 71-3 Pleasant Hill(Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Exterior (1480)-Other)	Accessibility Improvements, 71-3 Pleasant Hill		\$50,250.00
ID0044	Accessibility Improvements, 71-4 Griggsville(Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Site Work (1480)-Other)	Accessibility Improvements, 71-4 Griggsville		\$50,250.00

2577-0274 02/28/2022

Part II: Supporting Pages - Physical Needs Work Statements (s)

Work Statement for Year 2

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0045	Accessibility Improvements, 71-9 Pittsfield(Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Exterior (1480)-Other)	Accessibility Improvements, 71-9 Pittsfield		\$50,250.00
ID0046	Accessibility Improvements, 71-10 Barry(Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Exterior (1480)-Other)	Accessibility Improvements, 71-10 Barry		\$50,250.00
ID0047	Accessibility Improvements, 71-14 New Canton(Dwelling Unit-Exterior (1480)-Other, Dwelling Unit-Interior (1480)-Other, Dwelling Unit-Site Work (1480)-Other)	Accessibility Improvements, 71-14 New Canton		\$50,250.00
ID0048	Accessibility Improvements, 71-15 Pittsfield(Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Site Work (1480)-Other)	Accessibility Improvements, 71-15 Pittsfield		\$50,250.00
	Subtotal of Estimated Cost			\$596,000.00

Work Statement for Year 3

WOIR State	Work Statement for Teal 3 2020				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost	
	PITTSFIELD (IL071000001)			\$596,000.00	
ID0023	Parking Lot/Road Repair, 71-1 Barry(Non-Dwelling Site Work (1480)-Asphalt - Concrete - Paving,Non-Dwelling Site Work (1480)-Curb and Gutter)	Parking Lot/Road Repair, 71-1 Barry		\$134,000.00	
ID0029	Operations(Operations (1406))	Operations		\$149,000.00	
ID0030	A&E Costs(Contract Administration (1480)-Other Fees and Costs)	A&E Costs		\$45,000.00	
ID0049	Parking Lot/Road Repair, 71-3 Pleasant Hill(Non-Dwelling Site Work (1480)-Asphalt - Concrete - Paving,Non-Dwelling Site Work (1480)-Curb and Gutter)	Parking Lot/Road Repair, 71-3 Pleasant Hill		\$134,000.00	
ID0050	Parking Lot/Road Repair, 71-10 Barry(Non-Dwelling Site Work (1480)-Asphalt - Concrete - Paving,Non-Dwelling Site Work (1480)-Curb and Gutter)	Parking Lot/Road Repair, 71-10 Barry		\$134,000.00	
	Subtotal of Estimated Cost			\$596,000.00	

Work Statement for Year 4

			<u> </u>	
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	PITTSFIELD (IL071000001)			\$596,000.00
ID0036	Fascia Repair/Replace, Soffit Repair/Replace, Siding Repair/Replace, Tuckpointing, Gutter/Downspout Repair/Replace, 71-10 Barry(Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Tuck-Pointing)	Fascia Repair/Replace, Soffit Repair/Replace, Siding Repair/Replace, Tuckpointing, Gutter/Downspout Repair/Replace, 71-10 Barry		\$201,000.00
ID0037	Fascia Repair/Replace, Soffit Repair/Replace, Siding Repair/Replace, Tuckpointing, Gutter/Downspout Repair/Replace, 71-14 New Canton(Dwelling Unit-Exterior (1480)-Gutters - Downspouts, Dwelling Unit-Exterior (1480)-Siding, Dwelling Unit-Exterior (1480)-Soffits, Dwelling Unit-Exterior (1480)-Tuck-Pointing)	Fascia Repair/Replace, Soffit Repair/Replace, Siding Repair/Replace, Tuckpointing, Gutter/Downspout Repair/Replace, 71-14 New Canton		\$201,000.00
ID0038	Operations(Operations (1406))	Operations		\$149,000.00
ID0039	A&E Costs(Contract Administration (1480)-Other Fees and Costs)	A&E Costs		\$45,000.00
	Subtotal of Estimated Cost			\$596,000.00

Work Statement for Year 5

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	PITTSFIELD (IL071000001)			\$596,000.00
ID0040	Fascia Repair/Replace, Soffit Repair/Replace, Siding Repair/Replace, Tuckpointing, Gutter/Downspout Repair/Replace, 71-15 Pittsfield(Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Tuck-Pointing)	Fascia Repair/Replace, Soffit Repair/Replace, Siding Repair/Replace, Tuckpointing, Gutter/Downspout Repair/Replace, 71-15 Pittsfield		\$197,500.00
ID0051	Operations(Operations (1406))	Operations		\$149,000.00
ID0052	A&E Costs(Contract Administration (1480)-Other Fees and Costs)	A&E Costs		\$45,000.00
ID0053	Window Repair/Replace, 71-2 Barry(Dwelling Unit-Exterior (1480)-Windows)	Window Repair/Replace, 71-2 Barry		\$20,000.00
ID0054	Window Repair/Replace, 71-9 Pittsfield(Dwelling Unit-Exterior (1480)-Windows)	Window Repair/Replace, 71-9 Pittsfield		\$20,000.00
ID0055	Window Repair/Replace, 71-3 Pleasant Hill(Dwelling Unit-Exterior (1480)-Windows)	Window Repair/Replace, 71-3 Pleasant Hill		\$20,000.00

Work Statement for Year 5

Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
Roof Repair/Replace, 71-15 Pittsfield(Dwelling Unit-Exterior (1480)-Roofs)	Roof Repair/Replace, 71-15 Pittsfield		\$20,000.00
Exterior Door Repair/Replace, 71-1 Barry(Dwelling Unit-Exterior (1480)-Exterior Doors)	Exterior Door Repair/Replace, 71-1 Barry		\$5,000.00
Exterior Door Repair/Replace, 71-2 Barry(Dwelling Unit-Exterior (1480)-Exterior Doors)	Exterior Door Repair/Replace, 71-2 Barry		\$5,000.00
Exterior Door Repair/Replace, 71-3 Pleasant Hill(Dwelling Unit-Exterior (1480)-Exterior Doors)	Exterior Door Repair/Replace, 71-3 Pleasant Hill		\$5,000.00
Exterior Door Repair/Replace, 71-4 Griggsville(Dwelling Unit-Exterior (1480)-Exterior Doors)	Exterior Door Repair/Replace, 71-4 Griggsville		\$5,000.00
Exterior Door Repair/Replace, 71-9 Pittsfield(Dwelling Unit-Exterior (1480)-Exterior Doors)	Exterior Door Repair/Replace, 71-9 Pittsfield		\$5,000.00
Exterior Door Repair/Replace, 71-10 Barry(Dwelling Unit-Exterior (1480)-Exterior Doors)	Exterior Door Repair/Replace, 71-10 Barry		\$5,000.00
	Roof Repair/Replace, 71-15 Pittsfield(Dwelling Unit-Exterior (1480)-Roofs) Exterior Door Repair/Replace, 71-1 Barry(Dwelling Unit-Exterior (1480)-Exterior Doors) Exterior Door Repair/Replace, 71-2 Barry(Dwelling Unit-Exterior (1480)-Exterior Doors) Exterior Door Repair/Replace, 71-3 Pleasant Hill(Dwelling Unit-Exterior (1480)-Exterior Doors) Exterior Door Repair/Replace, 71-4 Griggsville(Dwelling Unit-Exterior (1480)-Exterior Doors) Exterior Door Repair/Replace, 71-9 Pittsfield(Dwelling Unit-Exterior (1480)-Exterior Doors)	Roof Repair/Replace, 71-15 Pittsfield(Dwelling Unit-Exterior (1480)-Roofs) Exterior Door Repair/Replace, 71-15 Pittsfield Exterior Door Repair/Replace, 71-2 Barry Exterior Door Repair/Replace, 71-2 Barry Exterior Door Repair/Replace, 71-3 Pleasant Hill Exterior Door Repair/Replace, 71-3 Pleasant Hill Exterior Door Repair/Replace, 71-4 Griggsville(Dwelling Unit-Exterior (1480)-Exterior Doors) Exterior Door Repair/Replace, 71-4 Griggsville Exterior Door Repair/Replace, 71-9 Pittsfield(Dwelling Unit-Exterior (1480)-Exterior Doors) Exterior Door Repair/Replace, 71-9 Pittsfield(Dwelling Unit-Exterior (1480)-Exterior Doors) Exterior Door Repair/Replace, 71-9 Pittsfield	Roof Repair/Replace, 71-15 Pittsfield(Dwelling Unit-Exterior (1480)-Roofs) Exterior Door Repair/Replace, 71-15 Pittsfield Exterior Door Repair/Replace, 71-1 Barry(Dwelling Unit-Exterior (1480)-Exterior Doors) Exterior Door Repair/Replace, 71-2 Barry(Dwelling Unit-Exterior (1480)-Exterior Doors) Exterior Door Repair/Replace, 71-2 Barry(Dwelling Unit-Exterior (1480)-Exterior Doors) Exterior Door Repair/Replace, 71-3 Pleasant Hill(Dwelling Unit-Exterior (1480)-Exterior Doors) Exterior Door Repair/Replace, 71-3 Pleasant Hill Exterior Door Repair/Replace, 71-4 Griggsville(Dwelling Unit-Exterior (1480)-Exterior Doors) Exterior Door Repair/Replace, 71-4 Griggsville Exterior Door Repair/Replace, 71-9 Pittsfield(Dwelling Unit-Exterior (1480)-Exterior Doors) Exterior Door Repair/Replace, 71-9 Pittsfield(Dwelling Unit-Exterior (1480)-Exterior Doors) Exterior Door Repair/Replace, 71-9 Pittsfield(Dwelling Unit-Exterior (1480)-Exterior Doors) Exterior Door Repair/Replace, 71-9 Pittsfield

Work Statement for Year 5

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0063	Exterior Door Repair/Replace, 71-14 New Canton(Dwelling Unit-Exterior (1480)-Exterior Doors)	Exterior Door Repair/Replace, 71-14 New Canton		\$5,000.00
ID0064	Exterior Door Repair/Replace, 71-15 Pittsfield(Dwelling Unit-Exterior (1480)-Exterior Doors)	Exterior Door Repair/Replace, 71-15 Pittsfield		\$5,000.00
ID0065	Bath Exhaust & Venting Repair/Replace, 71-1 Barry(Dwelling Unit-Interior (1480)-Mechanical)	Bath Exhaust & Venting Repair/Replace, 71-1 Barry		\$5,000.00
ID0066	Bath Exhaust & Venting Repair/Replace, 71-2 Barry(Dwelling Unit-Interior (1480)-Mechanical)	Bath Exhaust & Venting Repair/Replace, 71-2 Barry		\$5,000.00
ID0067	Bath Exhaust & Venting Repair/Replace, 71-3 Pleasant Hill(Dwelling Unit-Interior (1480)-Mechanical)	Bath Exhaust & Venting Repair/Replace, 71-3 Pleasant Hill		\$5,000.00
ID0068	Bath Exhaust & Venting Repair/Replace, 71-4 Griggsville(Dwelling Unit-Interior (1480)-Mechanical)	Bath Exhaust & Venting Repair/Replace, 71-4 Griggsville		\$5,000.00
ID0069	Bath Exhaust & Venting Repair/Replace, 71-9 Pittsfield(Dwelling Unit-Interior (1480)-Mechanical)	Bath Exhaust & Venting Repair/Replace, 71-9 Pittsfield		\$5,000.00

Work Statement for Year 5

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0070	Bath Exhaust & Venting Repair/Replace, 71-10 Barry(Dwelling Unit-Interior (1480)-Mechanical)	Bath Exhaust & Venting Repair/Replace, 71-10 Barry		\$5,000.00
ID0071	Bath Exhaust & Venting Repair/Replace, 71-14 New Canton(Dwelling Unit-Interior (1480)-Mechanical)	Bath Exhaust & Venting Repair/Replace, 71-14 New Canton		\$5,000.00
ID0072	Bath Exhaust & Venting Repair/Replace, 71-15 Pittsfield(Dwelling Unit-Interior (1480)-Mechanical)	Bath Exhaust & Venting Repair/Replace, 71-15 Pittsfield		\$5,000.00
ID0073	Kitchen Renovations - Cabinet, Countertop, Rangehood, Backsplash, Sink, Correct Venting (if necessary), etc., 71-2 Barry(Dwelling Unit-Interior (1480)-Kitchen Cabinets, Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets, Dwelling Unit-Interior (1480)-Mechanical, Dwelling Unit-Interior (1480)-Plumbing)	Kitchen Renovations - Cabinet, Countertop, Rangehood, Backsplash, Sink, Plumbing/Correct Venting (if necessary), etc., 71-2 Barry		\$14,833.34
ID0074	Kitchen Renovations - Cabinet, Countertop, Rangehood, Backsplash, Sink, Correct Venting (if necessary), etc., 71-3 Pleasant Hill(Dwelling Unit-Interior (1480)-Kitchen Cabinets, Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets, Dwelling Unit-Interior (1480)-Plumbing)	Kitchen Renovations - Cabinet, Countertop, Rangehood, Backsplash, Sink, Plumbing/Correct Venting (if necessary), etc., 71-3 Pleasant Hill		\$14,833.33
ID0075	Kitchen Renovations - Cabinet, Countertop, Rangehood, Backsplash, Sink, Correct Venting (if necessary), etc., 71-15 Pittsfield(Dwelling Unit-Interior (1480)-Kitchen Cabinets, Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets, Dwelling Unit-Interior (1480)-Mechanical, Dwelling Unit-Interior (1480)-Plumbing)	Kitchen Renovations - Cabinet, Countertop, Rangehood, Backsplash, Sink, Plumbing/Correct Venting (if necessary), etc., 71-15 Pittsfield		\$14,833.33
	Subtotal of Estimated Cost			\$596,000.00